


「物件調書」記載の区画 及び区画 の隣接地との境界において、一部構造物とのずれが生じていることについては、別添の現況写真（隣接地の構造物との境界のずれ）をご参照ください。

境界確認においては、別添の現況写真（境界点）を併せてご参照ください。

# 現況写真（隣接地の構造物との境界のずれ）

## 【区画①】



1 6 (→1 1 3)



1 1 3 (→1 6)

## 【区画④】



1 7 (→1 8)



1 7 (→1 8)



1 8 (→1 7)

# 現況写真（境界点）

【区画①】【区画②】



1 5



1 6




1 1 3



W700



W701



2 0

現況写真（境界点）



2 2



2 4

【区画③】



1 9



2 1



2 3 N-①



2 3 N-②

現況写真（境界点）



110N-①



110N-②



H370



H365



H361



H355

現況写真（境界点）

【区画④】



5



6 3



1 7



1 8



W 2



W 1